



Ten Oaks recommends the use of the Loba 2K Contact System

Recommendation for Recoating Ten Oaks Prefinished Flooring

Step One - Clean

For additional coats after installation, clean the floor with LOBA Hardwood Floor Cleaner. For recoating old, worn floors we recommend a deep cleaning with LOBA Remover. Apply LOBA® Remover diluted in water (1:5). Buff the damp surface with a red or maroon pad. Use a wet/dry vacuum or clean towels to remove the residue. Tack the floor with a clean towel and LOBA® Hardwood Floor Cleaner.

Step Two - Contact

Apply WS 2K Contact after the floor is dry and free of any dust. The application of WS 2K Contact adhesion promoter is very simple. Just mix component A and B together and apply a thin coat of LOBA 2K Contact over the floor using a trim pad or heavy T-bar applicator. The coverage rate of 2K Contact is approximately 350 sq ft/quart. Allow to dry for 2 hours or until thoroughly dry before top coating with Loba WS 2K Supra. Coating with Loba WS 2K Supra must be completed within 24 for best adhesion results.

Step Three - Coat

LOBA® WS 2K Supra is formulated for commercial high traffic floors and the only finish that works in combination with LOBA® WS 2K Contact. LOBA® WS 2K Supra is available in a variety of beautiful sheens and qualifies for LEED credit as an EQ 4.2 low emission coating. Apply one coat of 2K Supra with a roller, brush or T-bar applicator. Apply using 400-500 sq ft per gallon coverage. See the Loba website www.loba-wakol.com for more information.